



Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Tuesday, March 2, 2021	Project Contact:	Brian Clauto
Spread G: Craig Giles	ST11620-11600 ATWS 1370, 1370A, 1057, 1373 AR- MRV25, GI 234, GI249.01, 258.01	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply) ☐ Tree Felling ☐ Clearing/Grubbing ☐ Grading ☐ Trenching		Stringi	ng/Welding		
	\boxtimes	Dorma			
Yes	es N	No N	I/A		
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?					
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?					
3. Areas of offsite sediment deposition observed?		\boxtimes			
 <u>Comments:</u> Inspected the following resources: S-Q14, S-G32, S-RR13, S-RR14, S-006 ECD's were in place and functioning at the designated crossings. Routine Maintenance: (72-Hour Deadline from Notification) 					
- N/A Ineffective Controls: (<u>24-Hour Deadline</u> from Notification) - N/A					
Recommended Corrective Action: N/A					

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____

Date: Tuesday, March 2, 2021



FIELD INSPECTION PHOTO LOG

<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Tuesday, March 2, 2021

Figure 1: ECD's remain installed on AR-GI 234



Figure 2: Blanket matted remains installed at AR GI- 234



 Figure 3: Designated crossing S-G32, ECD's are in place and functioning.



Figure 4: Designated crossing S-006, ECD's are in place and functioning.

